

Outfall ID	Ammonia (mg/L)	Detergents - MBAS (ppm)	Temperature (C)	pH	Conductivity (uS)
QCH-PT-001	0	0.5	15	7.67	131
QCH-PT-002	0.1	0	13.7	7.55	137
QCH-PT-003	0	0.25	15.3	7.88	438
QCH-PT-004	0.08	0	15.7	7.89	370
QCH-PT-005	0	0	16.6	7.78	330
QCH-PT-006	Originally thought this outfall was HRT-OF-95. No flow when checked before. No flow now. Some stagnant water. Not sampled.				
QCH-PT-007	0.4	0	20.3	7.83	404
QCH-PT-008	No flow was present. No sample was taken.				

N

0 0.25 0.5 Miles

White River Basin IDDE
Quechee Stream Testing

WATERSHED CONSULTING ASSOCIATES, LLC

Map Produced: 7/31/2017