


North Bennington/Bennington PFOA

Water Sampling Test Results - June 8, 2016



MAP LEGEND

- | | | | |
|---------------|------------------------------------------------------------------|----------------------------|------------------------------------------------------------------------------|
| PFOA | ● Non-Detect (ND) | BOUNDARIES | □ Village Boundary (VCGI) |
| | ● <20 ppt (VDH Advisory) | | □ Sampling Boundary |
| | ● 20 - 70 ppt | | □ 6/22/16 Sampling Extension |
| | ● 70 - 1000 ppt | | □ 5/24/16 Sampling Extension |
| | ● >1000 ppt | | □ Town Boundary |
| LAYERS | ▲ Landfill Monitoring | Factory | |
| | Landfill | Wastewater Treatment Plant | |
| | Town Water Sample | WaterLine | |
| | | | |
| | | | |

Notes:
 Sources: Roads (VTRANS), Basemap (VCGI), Geocoding Service (VCGI), Sampling Results (VTDEC/Weston & Sampson), Waterline (Otter Creek Engineering), Streams and Waterbodies (NHD).

Sampling locations are determined by geocoded addresses as provided. Latitude/Longitude used in instances where well locations were recorded.

0 0.3 0.6 1.2 1.8 2.4
Miles