

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

Sample Date	Street Name	PFOA	PFHpA	PFOS	
3/8/2016	Airport Road	ND/<6.7	ND/<3.3	ND/<13	
3/8/2016	Airport Road	ND/<6.7	ND/<3.3	ND/<13	
3/22/2016	Airport Road	ND/<6.7	ND/<3.3	ND/<13	
4/13/2016	Airport Road	ND/<6.7	ND/<3.3	ND/<13	
5/2/2016	Andre Lane	ND/<6.7	ND/<3.3	ND/<13	
4/12/2016	Apple Hill Road	144	9.11	ND/<13	
4/12/2016	Apple Hill Road	143	8.78	ND/<13	
4/12/2016	Apple Hill Road	139	5.51	ND/<13	
4/12/2016	Apple Hill Road	90.7	5.86	ND/<13	
4/13/2016	Apple Hill Road	132	7.21	ND/<13	
4/13/2016	Apple Hill Road	146	7.61	ND/<13	
4/13/2016	Apple Hill Road	167	8.0	ND/<13	
4/13/2016	Apple Hill Road	32.7	ND/<3.3	ND/<13	
4/14/2016	Apple Hill Road	104	5.96	ND/<13	
4/19/2016	Apple Hill Road	102	5.97	ND/<13	
4/20/2016	Apple Hill Road	179	10.2	ND/<13	
5/2/2016	Apple Hill Road	53.6	5.36	ND/<13	
2/15/2016	Asa Way	2,330	81.4	ND/<13	
3/1/2016	Asa Way	2,000	52.5	ND/<13	
3/1/2016	Asa Way	82.6	5.61	ND/<13	
3/1/2016	Asa Way	223	11.9	ND/<13	
3/1/2016	Asa Way	370	18.9	ND/<13	
3/1/2016	Asa Way	293	14.7	ND/<13	
5/10/2016	Asa Way	291	16.1	ND/<13	
4/12/2016	Astrachan Drive	90.4	4.33	ND/<13	
4/12/2016	Astrachan Drive	168	7.84	ND/<13	
4/13/2016	Astrachan Drive	96	4.07	ND/<13	
4/13/2016	Astrachan Drive	155	11.2	ND/<13	
3/1/2016	Austin Hill Road	ND/<6.7	ND/<3.3	ND/<13	
3/1/2016	Austin Hill Road	238	10.8	ND/<13	
3/1/2016	Austin Hill Road	60.6	ND/<3.3	ND/<13	
3/1/2016	Austin Hill Road	62.3	ND/<3.3	ND/<13	
3/3/2016	Austin Hill Road	ND/<6.7	ND/<3.3	ND/<13	
3/8/2016	Austin Hill Road	94.5	5.58	ND/<13	
3/8/2016	Austin Hill Road	241	9.5	ND/<13	
3/21/2016	Austin Hill Road	ND/<6.7	ND/<3.3	ND/<13	
3/31/2016	Austin Hill Road	118	5.48	ND/<13	
5/10/2016	Austin Hill Road	92.5	5.81	ND/<13	
4/12/2016	Autumn Acres	ND/<6.7	ND/<3.3	ND/<13	
4/19/2016	Autumn Acres	37.4	ND/<3.3	ND/<13	
3/9/2016	Bank Street	ND/<6.7	ND/<3.3	ND/<13	
3/22/2016	Bank Street	30	ND/<3.3	ND/<13	
3/4/2016	Bard Road	230	13.7	ND/<13	
3/4/2016	Bard Road	140	8.21	ND/<13	
3/4/2016	Bard Road	217	13.1	ND/<13	
3/4/2016	Bard Road	11.1	ND/<3.3	ND/<13	
3/4/2016	Bard Road	149	7.18	ND/<13	
3/4/2016	Bard Road	ND/<6.7	ND/<3.3	ND/<13	

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

3/4/2016	Bard Road	7.83	ND/<3.3	ND/<13
3/4/2016	Bard Road	<b>139</b>	7.9	ND/<13
3/4/2016	Bard Road	<b>383</b>	20.3	ND/<13
3/8/2016	Bard Road	<b>192</b>	9.6	ND/<13
3/23/2016	Bard Road	9.5	ND/<3.3	ND/<13
3/23/2016	Bard Road	9.0	ND/<3.3	ND/<13
4/13/2016	Becks Drive	<b>52.9</b>	ND/<3.3	ND/<13
3/3/2016	Bridge Street	<b>85.9</b>	4.65	ND/<13
3/3/2016	Bridge Street	<b>76.2</b>	8.94	ND/<13
3/3/2016	Buckhill Road -town water	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Cardinal Lane	<b>124</b>	3.52	ND/<13
3/8/2016	Cardinal Lane	<b>100</b>	ND/<3.3	ND/<13
3/8/2016	Cardinal Lane	<b>31.8</b>	ND/<3.3	ND/<13
3/21/2016	Cardinal Lane	<b>120</b>	6.55	ND/<13
3/21/2016	Cardinal Lane	<b>78.8</b>	4.13	ND/<13
3/21/2016	Cardinal Lane	<b>224</b>	7.89	ND/<13
4/14/2016	Cardinal Lane	<b>20.2</b>	ND/<3.3	ND/<13
6/1/2016	Chapel Road	<b>21.6</b>	4.09	ND/<13
6/1/2016	Chapel Road	12.6	ND/<3.3	ND/<13
6/1/2016	Chapel Road	19.4	ND/<3.3	ND/<13
6/7/2016	Chapel Road	<b>129</b>	13.1	ND/<13
6/7/2016	Chapel Road	<b>50.2</b>	ND/<3.3	ND/<13
6/30/2016	Chapel Road	<b>27.9</b>	ND/<3.3	ND/<13
6/30/2016	Chapel Road	7.28	ND/<3.3	ND/<13
7/1/2016	Chapel Road	<b>38.8</b>	ND/<3.3	ND/<13
7/1/2016	Chapel Road	6.95	ND/<3.3	ND/<13
7/1/2016	Chapel Road	ND/<6.7	ND/<3.3	ND/<13
7/1/2016	Chapel Road	17.9	ND/<3.3	ND/<13
6/30/2016	Church Lane	10.7	ND/<3.3	ND/<13
5/11/2016	Cold Spring Road	ND/<6.7	ND/<3.3	ND/<13
4/12/2016	Cortland Lane	<b>105</b>	6.81	ND/<13
4/13/2016	Cortland Lane	<b>72.6</b>	4.58	ND/<13
4/13/2016	Cortland Lane	<b>93.4</b>	6.45	ND/<13
4/12/2016	Cory Lane	ND/<6.7	ND/<3.3	ND/<13
5/3/2016	Dermody Road	ND/<6.7	ND/<3.3	ND/<13
5/10/2016	East Road	<b>69</b>	6.48	ND/<13
5/10/2016	East Road	ND/<6.7	ND/<3.3	ND/<13
5/10/2016	East Road	18.7	ND/<3.3	ND/<13
5/11/2016	East Road	<b>64.3</b>	5.17	ND/<13
5/11/2016	East Road	<b>24.5</b>	ND/<3.3	ND/<13
6/1/2016	East Road	11.2	ND/<3.3	ND/<13
6/1/2016	East Road	14.6	ND/<3.3	ND/<13
6/8/2016	East Road	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	East Road	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	East Road	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	East Road	<b>28.8</b>	ND/<3.3	ND/<13
3/21/2016	Eaton Road	<b>79</b>	ND/<3.3	ND/<13
3/21/2016	Eaton Road	<b>136</b>	6.29	ND/<13
3/22/2016	Eaton Road	<b>96.6</b>	4.35	ND/<13

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

3/3/2016	Edith Way	<b>387</b>	9.02	ND/<13
3/3/2016	Edith Way	<b>62.0</b>	ND/<3.3	ND/<13
4/13/2016	Fairview street	<b>71.7</b>	4.43	ND/<13
4/13/2016	Fairview street	<b>23.3</b>	ND/<3.3	ND/<13
5/11/2016	Fairview street	<b>41.7</b>	ND/<3.3	ND/<13
5/3/2016	Fox Hill Road	ND/<6.7	ND/<3.3	ND/<13
5/3/2016	Fox Hill Road	ND/<6.7	ND/<3.3	ND/<13
5/3/2016	Fox Hill Road	ND/<6.7	ND/<3.3	ND/<13
5/4/2016	Fox Hill Road	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	Furnace Brook Rd	ND/<6.7	ND/<3.3	ND/<13
4/20/2016	Garden Lane	ND/<6.7	ND/<3.3	ND/<13
5/3/2016	Gypsy Lane	7.49	ND/<3.3	ND/<13
5/3/2016	Gypsy Lane	ND/<6.7	ND/<3.3	ND/<13
5/3/2016	Gypsy Lane	<b>28.8</b>	ND/<3.3	ND/<13
5/11/2016	Gypsy Lane	13.6	ND/<3.3	ND/<13
5/11/2016	Gypsy Lane	8.71	ND/<3.3	ND/<13
5/11/2016	Gypsy Lane	ND/<6.7	ND/<3.3	ND/<13
2/15/2016	Harrington Road	<b>153</b>	4.3	ND/<13
3/1/2016	Harrington Road	<b>362</b>	14.5	ND/<13
3/1/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/1/2016	Harrington Road	14.2	ND/<3.3	ND/<13
3/1/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Harrington Road	<b>1410</b>	57.5	ND/<13
3/2/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Harrington Road	<b>82.2</b>	3.65	ND/<13
3/3/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Harrington Road	<b>2,730</b>	97.8	ND/<13
3/3/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/4/2016	Harrington Road	<b>124</b>	6.1	ND/<13
3/8/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Harrington Road	ND/<6.7	ND/<3.3	ND/<13
3/22/2016	Harrington Road	<b>21.7</b>	ND/<3.3	ND/<13
3/22/2016	Harrington Road	14.4	ND/<3.3	ND/<13
3/28/2016	Harwood Hill Road	ND/<2.0	ND/<1.0	ND/<4
4/14/2016	Harwood Hill Road	<b>180</b>	11.3	ND/<13
4/19/2016	Harwood Hill Road	<b>46.6</b>	6.39	ND/<13
5/2/2016	Harwood Hill Road	29.6	ND/<3.3	ND/<13
5/3/2016	Harwood Hill Road	8.72	ND/<3.3	ND/<13
5/3/2016	Harwood Hill Road	<b>67.2</b>	4.74	ND/<13
5/3/2016	Harwood Hill Road	<b>91.5</b>	5.3	ND/<13
5/3/2016	Harwood Hill Road	<b>79.3</b>	4.61	ND/<13
5/4/2016	Harwood Hill Road	<b>123</b>	5.5	ND/<13
5/10/2016	Harwood Hill Road	ND/<6.7	ND/<3.3	ND/<13
5/11/2016	Harwood Hill Road	<b>132</b>	6.65	ND/<13

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

5/11/2016	Harwood Hill Road	9.49	ND/<3.3	ND/<13
5/11/2016	Harwood Hill Road	ND/<6.7	ND/<3.3	ND/<13
5/31/2016	Harwood Hill Road	ND/<6.7	ND/<3.3	ND/<13
6/1/2016	Harwood Hill Road	<b>111</b>	7.75	ND/<13
6/1/2016	Harwood Hill Road	<b>110</b>	8.36	ND/<13
6/1/2016	Harwood Hill Road	<b>88.9</b>	7.61	ND/<13
6/7/2016	Harwood Hill Road	7.57	ND/<3.3	ND/<13
6/7/2016	Harwood Hill Road	ND/<6.7	ND/<3.3	ND/<13
6/7/2016	Harwood Hill Road	ND/<6.7	ND/<3.3	ND/<13
7/1/2016	Harwood Hill Road	<b>92.7</b>	4.54	ND/<13
7/1/2016	Harwood Hill Road	<b>73.8</b>	4.59	ND/<13
4/13/2016	Hill Shadow Farm Road	<b>27.1</b>	ND/<3.3	ND/<13
4/13/2016	Hill Shadow Farm Road	17.5	ND/<3.3	ND/<13
4/13/2016	Hill Shadow Farm Road	<b>63.4</b>	ND/<3.3	ND/<13
5/2/2016	Hill Shadow Farm Road	<b>30.8</b>	ND/<3.3	ND/<13
5/2/2016	Hill Shadow Farm Road	<b>30.7</b>	ND/<3.3	ND/<13
5/10/2016	Hill Shadow Farm Road	<b>35.3</b>	ND/<3.3	ND/<13
3/23/2016	Horton Hill Road	ND/<6.7	ND/<3.3	ND/<13
3/23/2016	Horton Hill Road	ND/<6.7	ND/<3.3	ND/<13
3/23/2016	Horton Hill Road	ND/<6.7	ND/<3.3	ND/<13
4/12/2016	Houghton Lane	<b>114</b>	4.89	ND/<13
4/19/2016	Houghton Lane	<b>26.4</b>	ND/<3.3	ND/<13
5/3/2016	Houghton Lane	<b>112</b>	4.06	ND/<13
5/4/2016	Houghton Lane	ND/<6.7	ND/<3.3	ND/<13
5/10/2016	Houghton Lane	<b>113</b>	6.64	ND/<13
5/10/2016	Houghton Lane	<b>119</b>	5.88	ND/<13
5/11/2016	Houghton Lane	ND/<6.7	ND/<3.3	ND/<13
4/13/2016	Jennings Drive	19	ND/<3.3	ND/<13
4/13/2016	Jennings Drive	8.5	ND/<3.3	ND/<13
4/13/2016	Jennings Drive	12.2	ND/<3.3	ND/<13
4/19/2016	Jennings Drive	ND/<6.7	ND/<3.3	ND/<13
5/2/2016	Jennings Drive	ND/<6.7	ND/<3.3	ND/<13
5/2/2016	Jennings Drive	ND/<6.7	ND/<3.3	ND/<13
5/2/2016	Jennings Drive	18.5	3.73	ND/<13
5/3/2016	Jennings Drive	15.4	ND/<3.3	ND/<13
5/31/2016	Jennings Drive	ND/<6.7	ND/<3.3	ND/<13
5/31/2016	Jennings Drive	12	ND/<3.3	ND/<13
5/31/2016	Jennings Drive	7.83	ND/<3.3	ND/<13
5/31/2016	Jennings Drive	12.7	ND/<3.3	ND/<13
6/1/2016	Jennings Drive	7.88	ND/<3.3	ND/<13
6/30/2016	Jennings Drive	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	Jennings Drive	8.39	ND/<3.3	ND/<13
3/9/2016	Matt Drive	ND/<6.7	ND/<3.3	ND/<13
3/9/2016	Matt Drive	16.2	ND/<3.3	ND/<13
3/22/2016	Matt Drive	ND/<6.7	ND/<3.3	ND/<13
3/22/2016	Matt Drive	19.2	ND/<3.3	ND/<13
3/2/2016	Matteson Road	<b>124</b>	8.82	ND/<13
3/2/2016	Matteson Road	<b>215</b>	18.3	ND/<13
3/3/2016	Matteson Road	<b>249</b>	9.56	ND/<13

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

3/8/2016	Matteson Road	ND/<6.7	ND/<3.3	ND/<13
4/13/2016	Matteson Road	<b>108</b>	6.61	ND/<13
6/8/2016	Matteson Road	<b>229</b>	9.05	ND/<13
3/8/2016	McCullough Road	<b>86</b>	ND/<3.3	ND/<13
4/13/2016	McIntosh Lane	8.43	ND/<3.3	ND/<13
4/13/2016	McIntosh Lane	<b>201</b>	10	ND/<13
4/19/2016	McIntosh Lane	<b>75.5</b>	4.24	ND/<13
5/3/2016	McIntosh Lane	<b>118</b>	5.63	ND/<13
6/1/2016	McIntosh Lane	<b>61.3</b>	4.52	ND/<13
6/8/2016	McIntosh Lane	<b>78.2</b>	4.64	ND/<13
3/21/2016	Michaels Drive	<b>59.4</b>	4.73	ND/<13
4/12/2016	Michaels Drive	<b>50.1</b>	ND/<3.3	ND/<13
4/12/2016	Michaels Drive	<b>88</b>	5.19	ND/<13
4/12/2016	Michaels Drive	<b>105</b>	5.25	ND/<13
4/13/2016	Michaels Drive	<b>146</b>	6.69	ND/<13
4/13/2016	Michaels Drive	<b>22.5</b>	ND/<3.3	ND/<13
4/14/2016	Michaels Drive	<b>107</b>	4.12	ND/<13
4/20/2016	Michaels Drive	<b>24.4</b>	ND/<3.3	ND/<13
5/2/2016	Michaels Drive	<b>76.1</b>	3.37	ND/<13
5/2/2016	Michaels Drive	<b>35.2</b>	ND/<3.3	ND/<13
5/2/2016	Michaels Drive	<b>151</b>	7.13	ND/<13
3/1/2016	Murphy Road	<b>535</b>	19.8	ND/<13
3/1/2016	Murphy Road	<b>338</b>	9.97	ND/<13
3/1/2016	Murphy Road	<b>181</b>	7.44	ND/<13
3/2/2016	Murphy Road	<b>172</b>	6.8	ND/<13
3/2/2016	Murphy Road	<b>146</b>	7.28	ND/<13
3/2/2016	Murphy Road	<b>296</b>	11.9	ND/<13
3/2/2016	Murphy Road	<b>267</b>	11.2	ND/<13
3/2/2016	Murphy Road	<b>198</b>	7.46	ND/<13
3/2/2016	Murphy Road	<b>335</b>	11.9	ND/<13
3/2/2016	Murphy Road	<b>194</b>	6.72	ND/<13
3/2/2016	Murphy Road	<b>31.7</b>	ND/<3.3	ND/<13
3/2/2016	Murphy Road	<b>438</b>	19.5	<b>19.7</b>
3/3/2016	Murphy Road	<b>198</b>	9.6	ND/<13
3/3/2016	Murphy Road	<b>183</b>	8.62	ND/<13
3/3/2016	Murphy Road	10.1	ND/<3.3	ND/<13
3/4/2016	Murphy Road	<b>215</b>	10.1	ND/<13
3/22/2016	Murphy Road	<b>471</b>	22.5	ND/<13
3/23/2016	Murphy Road	11.3	ND/<3.3	ND/<13
3/31/2016	Murphy Road	<b>264</b>	9.04	ND/<13
3/1/2016	North Bennington Road	<b>446</b>	21.2	ND/<13
3/1/2016	North Bennington Road	<b>216</b>	7.56	ND/<13
3/1/2016	North Bennington Road	<b>189</b>	8.24	ND/<13
3/1/2016	North Bennington Road	<b>408</b>	18.4	ND/<13
3/1/2016	North Bennington Road	<b>1060</b>	28.4	ND/<13
3/1/2016	North Bennington Road	<b>302</b>	11.9	ND/<13
3/1/2016	North Bennington Road	<b>245</b>	12.3	ND/<13
3/1/2016	North Bennington Road	<b>301</b>	12.4	ND/<13
3/1/2016	North Bennington Road	<b>348</b>	14.7	ND/<13

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

3/1/2016	North Bennington Road	362	16.6	ND/<13
3/1/2016	North Bennington Road	362	16.6	ND/<13
3/1/2016	North Bennington Road	142	7.8	ND/<13
3/1/2016	North Bennington Road	ND/<6.7	ND/<3.3	ND/<13
3/1/2016	North Bennington Road	1070	32	ND/<13
3/1/2016	North Bennington Road	644	26.6	ND/<13
3/1/2016	North Bennington Road	373	ND/<3.3	ND/<13
3/2/2016	North Bennington Road	60.3	ND/<3.3	ND/<13
3/2/2016	North Bennington Road	74.4	ND/<3.3	ND/<13
3/2/2016	North Bennington Road	162	9.28	ND/<13
3/2/2016	North Bennington Road	314	21.6	ND/<13
3/2/2016	North Bennington Road	239	13.2	ND/<13
3/2/2016	North Bennington Road	410	19	ND/<13
3/2/2016	North Bennington Road	507	21.5	ND/<13
3/2/2016	North Bennington Road	564	37.2	ND/<13
3/2/2016	North Bennington Road	800	31	ND/<13
3/2/2016	North Bennington Road	13.5	ND/<3.3	ND/<13
3/2/2016	North Bennington Road	932	31.4	ND/<13
3/3/2016	North Bennington Road	106	4.49	ND/<13
3/3/2016	North Bennington Road	591	28.5	ND/<13
3/22/2016	North Bennington Road	346	19.2	ND/<13
3/22/2016	North Bennington Road	280	12.9	ND/<13
3/23/2016	North Bennington Road	220	14.6	ND/<13
3/23/2016	North Bennington Road	ND/<6.7	ND/<3.3	ND/<13
3/23/2016	North Bennington Road	1020	30.6	ND/<13
4/19/2016	North Bennington Road	ND/<6.7	ND/<3.3	ND/<13
6/1/2016	North Bennington Road	147	7.0	ND/<13
3/2/2016	Northside Drive	73	4.48	ND/<13
3/31/2016	Northside Drive	8.11	ND/<3.3	ND/<13
3/1/2016	Ore Bed Road	504	17.2	ND/<13
3/1/2016	Ore Bed Road	342	11.7	ND/<13
3/2/2016	Ore Bed Road	12.2	ND/<3.3	ND/<13
3/2/2016	Ore Bed Road	397	15.5	ND/<13
3/2/2016	Ore Bed Road	548	21.5	ND/<13
3/2/2016	Ore Bed Road	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Ore Bed Road	109	4.99	ND/<13
3/3/2016	Ore Bed Road	ND/<6.7	ND/<3.3	ND/<13
3/9/2016	Ore Bed Road	ND/<6.7	ND/<3.3	ND/<13
3/23/2016	Ore Bed Road	8.7	ND/<3.3	ND/<13
6/30/2016	Ore Bed Road	313	13	ND/<13
7/1/2016	Outwater Rd	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Overlea Road	ND/<6.7	ND/<3.3	ND/<13
3/6/2016	Overlea Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Overlea Road	ND/<6.7	ND/<3.3	ND/<13
4/19/2016	Overlea Road	15.2	ND/<3.3	ND/<13
5/3/2016	Overlea Road	ND/<6.7	ND/<3.3	ND/<13
5/10/2016	Overlea Road	19.3	ND/<3.3	ND/<13
6/7/2016	Overlea Road	20.6	ND/<3.3	ND/<13
6/30/2016	Overlea Road	8.78	ND/<3.3	ND/<13

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

3/1/2016	Park Street	<b>649</b>	25.5	ND/<13
4/12/2016	Pippin Knoll Road	15.4	ND/<3.3	ND/<13
4/12/2016	Pippin Knoll Road	<b>77.3</b>	ND/<3.3	ND/<13
4/12/2016	Pippin Knoll Road	<b>32.5</b>	ND/<3.3	ND/<13
4/13/2016	Pippin Knoll Road	<b>34.2</b>	ND/<3.3	ND/<13
4/13/2016	Pippin Knoll Road	<b>47.8</b>	ND/<3.3	ND/<13
5/4/2016	Pippin Knoll Road	<b>70.2</b>	3.55	ND/<13
6/7/2016	Pippin Knoll Road	<b>28.9</b>	ND/<3.3	ND/<13
3/4/2016	Red Pine Road	<b>126</b>	4.41	ND/<13
3/31/2016	Red Pine Road	15.8	ND/<3.3	ND/<13
4/12/2016	Red Pine Road	<b>62.5</b>	ND/<3.3	ND/<13
6/7/2016	Red Pine Road	<b>62.6</b>	ND/<3.3	<b>131</b>
5/4/2016	Regwood Dr	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Rice Lane	14.4	ND/<3.3	ND/<13
3/8/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/21/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
3/23/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
6/1/2016	Rice Lane	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	Rice Lane	<b>160</b>	10.7	ND/<13
3/1/2016	River Road	7.66	ND/<3.3	ND/<13
3/1/2016	River Road	<b>100</b>	4.7	ND/<13
3/22/2016	River Road	ND/<6.7	ND/<3.3	ND/<13
3/22/2016	River Road	ND/<6.7	ND/<3.3	ND/<13
3/23/2016	River Road	8.8	ND/<3.3	ND/<13
3/23/2016	River Road	ND/<6.7	ND/<3.3	ND/<13
3/31/2016	River Road	<b>261</b>	10.1	ND/<13
3/2/2016	Riverside Drive	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	Riverside Drive	<b>317</b>	13.1	ND/<13
3/2/2016	Riverside Drive	<b>413</b>	15	ND/<13
3/2/2016	Riverside Drive	<b>458</b>	16.8	ND/<13
4/13/2016	Rocky Lane	13.3	ND/<3.3	ND/<13
4/19/2016	Rocky Lane	<b>29.6</b>	ND/<3.3	ND/<13
5/4/2016	Rocky Lane	ND/<6.7	ND/<3.3	ND/<13
5/4/2016	Rocky Lane	8.65	ND/<3.3	ND/<13
5/4/2016	Rocky Lane	ND/<6.7	ND/<3.3	ND/<13
6/1/2016	Rocky Lane	ND/<6.7	ND/<3.3	ND/<13
6/8/2016	Rocky Lane	ND/<6.7	ND/<3.3	ND/<13
7/1/2016	Rocky Lane	<b>46.6</b>	10.2	ND/<13

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

5/11/2016	Rollin Road	ND/<6.7	ND/<3.3	ND/<13
5/11/2016	Rollin Road	ND/<6.7	ND/<3.3	ND/<13
5/11/2016	Rollin Road	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Route 67E	ND/<6.7	ND/<3.3	ND/<13
3/4/2016	Route 67E	ND/<6.7	ND/<3.3	ND/<13
3/6/2016	Route 67W	<b>67.7</b>	8.11	ND/<13
3/9/2016	Route 67W	ND/<6.7	ND/<3.3	ND/<13
3/9/2016	Route 67W	ND/<6.7	ND/<3.3	ND/<13
3/22/2016	Route 67W	ND/<6.7	ND/<3.3	ND/<13
3/22/2016	Route 67W	<b>40.4</b>	ND/<3.3	ND/<13
3/22/2016	Route 67W	ND/<6.7	ND/<3.3	ND/<13
3/31/2016	Route 67W	ND/<6.7	ND/<3.3	ND/<13
3/31/2016	Route 67W	ND/<6.7	ND/<3.3	ND/<13
3/31/2016	Route 67W	ND/<6.7	ND/<3.3	ND/<13
4/13/2016	Route 67W	14.4	ND/<3.3	ND/<13
4/14/2016	Route 67W	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	Route 67W	ND/<6.7	ND/<3.3	ND/<13
3/31/2016	Route 9	ND/<6.7	ND/<3.3	ND/<13
3/31/2016	Route 9	ND/<6.7	ND/<3.3	ND/<13
3/31/2016	Route 9	ND/<6.7	ND/<3.3	ND/<13
3/1/2016	Royal Street	<b>1150</b>	42.1	ND/<13
3/1/2016	Royal Street	<b>2270</b>	50.5	ND/<13
3/1/2016	Royal Street	<b>647</b>	22.9	ND/<13
4/12/2016	Russett Drive	<b>64.8</b>	ND/<3.3	ND/<13
4/12/2016	Russett Drive	<b>92.1</b>	4.9	ND/<13
4/13/2016	Russett Drive	10.9	ND/<3.3	ND/<13
4/13/2016	Russett Drive	<b>146</b>	6.98	ND/<13
4/14/2016	Russett Drive	<b>102</b>	5.42	ND/<13
4/19/2016	Russett Drive	<b>86.4</b>	4.73	ND/<13
5/2/2016	Russett Drive	<b>115</b>	5.68	ND/<13
2/15/2016	Scarey Lane	<b>41</b>	ND/<3.3	ND/<13
3/1/2016	Scarey lane	<b>37.9</b>	ND/<3.3	ND/<13
3/4/2016	Scarey Lane	ND/<6.7	ND/<3.3	ND/<13
3/2/2016	School Street Village School	ND/<6.7	ND/<3.3	ND/<13
3/9/2016	Settlers Road	ND/<6.7	ND/<3.3	ND/<13
5/3/2016	Settlers Road	14.4	ND/<3.3	ND/<13
5/31/2016	Settlers Road	<b>43</b>	ND/<3.3	ND/<13
6/7/2016	Settlers Road	<b>381</b>	ND/<3.3	ND/<13
6/8/2016	Settlers Road	<b>65.8</b>	4.65	ND/<13
6/8/2016	Settlers Road	<b>23.8</b>	ND/<3.3	ND/<13
6/8/2016	Settlers Road	ND/<6.7	ND/<3.3	ND/<13
6/8/2016	Settlers Road	ND/<6.7	ND/<3.3	ND/<13
7/1/2016	Settlers Road	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Silk Road	<b>170</b>	7.2	ND/<13
3/3/2016	Silk Road	<b>223</b>	11.4	ND/<13
3/3/2016	Silk Road	<b>293</b>	16.2	ND/<13
3/3/2016	Silk Road	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Silk Road	<b>71.3</b>	3.93	ND/<13
3/3/2016	Silk Road	<b>297</b>	14.3	ND/<13



# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

3/3/2016	Silk Road	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Silk Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Silk Road	ND/<6.7	ND/<3.3	ND/<13
3/9/2016	Silk Road	ND/<6.7	ND/<3.3	ND/<13
3/21/2016	Silk Road	<b>174</b>	7.76	ND/<13
3/21/2016	Silk Road	10.5	ND/<3.3	ND/<13
3/21/2016	Silk Road	ND/<6.7	ND/<3.3	ND/<13
3/21/2016	Silk Road	<b>179</b>	8.72	ND/<13
3/21/2016	Silk Road	<b>280</b>	15.1	ND/<13
3/31/2016	Silk Road	ND/<6.7	ND/<3.3	ND/<13
4/20/2016	Silk Road	17.5	ND/<3.3	ND/<13
6/30/2016	South Stateline Rd	ND/<6.7	ND/<3.3	ND/<13
5/31/2016	Spring Hill Road	ND/<6.7	ND/<3.3	ND/<13
5/31/2016	Spring Hill Road	ND/<6.7	ND/<3.3	ND/<13
5/31/2016	Spring Hill Road	<b>62.3</b>	5.81	ND/<13
6/7/2016	Spring Hill Road	15.9	ND/<3.3	ND/<13
6/30/2016	Spring Hill Road	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	Spring Hill Road	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	Spring Hill Road	ND/<6.7	ND/<3.3	ND/<13
5/2/2016	Squaw Hill Road	<b>111</b>	4.23	ND/<13
5/3/2016	Squaw Hill Road	<b>67.9</b>	ND/<3.3	ND/<13
4/13/2016	Sugar Maple Lane	ND/<6.7	ND/<3.3	ND/<13
2/15/2016	Susan Taylor Lane	<b>422</b>	12.2	ND/<13
3/1/2016	Susan Taylor Lane	<b>2090</b>	103	ND/<13
3/1/2016	Susan Taylor Lane	<b>120</b>	8.24	ND/<13
3/1/2016	Susan Taylor Lane	7.09	ND/<3.3	ND/<13
3/1/2016	Susan Taylor Lane	<b>580</b>	23.9	ND/<13
3/3/2016	Susan Taylor Lane	<b>322</b>	9.38	ND/<13
3/23/2016	Susan Taylor Lane	ND/<6.7	ND/<3.3	ND/<13
4/13/2016	Susan Taylor Lane	<b>780</b>	28.7	ND/<13
5/11/2016	Townline Road	ND/<6.7	ND/<3.3	ND/<13
6/1/2016	Townline Road	ND/<6.7	ND/<3.3	ND/<13
6/7/2016	Townline Road	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	TownLine Road	ND/<6.7	ND/<3.3	ND/<13
6/30/2016	TownLine Road	ND/<6.7	ND/<3.3	ND/<13
7/1/2016	TownLine Road	<b>24.8</b>	ND/<3.3	ND/<13
6/7/2016	Transport Drive	<b>69.3</b>	3.48	ND/<13
3/1/2016	Vail Road	<b>50.8</b>	ND/<3.3	ND/<13
3/1/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/1/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Vail Road	<b>44.8</b>	ND/<3.3	ND/<13
3/3/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/3/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/4/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

3/8/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/8/2016	Vail Road	<b>150</b>	4.24	ND/<13
3/9/2016	Vail Road	<b>25.1</b>	ND/<3.3	ND/<13
3/21/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/21/2016	Vail Road	<b>31.4</b>	ND/<3.3	ND/<13
3/21/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/21/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/23/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
3/23/2016	Vail Road	14.3	ND/<3.3	ND/<13
4/12/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
4/12/2016	Vail Road	19	ND/<3.3	ND/<13
4/19/2016	Vail Road	<b>489</b>	19.1	ND/<13
4/19/2016	Vail Road	ND/<6.7	ND/<3.3	ND/<13
5/4/2016	Vail Road	13.8	ND/<3.3	ND/<13
6/1/2016	Vail Road	16.6	ND/<3.3	ND/<13
5/3/2016	Village Lane	9.35	ND/<3.3	ND/<13
5/4/2016	Village Lane	ND/<6.7	ND/<3.3	ND/<13
4/12/2016	Walloomsac Road	8.71	ND/<3.3	ND/<13
4/12/2016	Walloomsac Road	<b>50.9</b>	5.06	ND/<13
4/12/2016	Walloomsac Road	<b>21.1</b>	ND/<3.3	ND/<13
5/2/2016	Walloomsac Road	<b>41.3</b>	ND/<3.3	ND/<13
5/2/2016	Walloomsac Road	18.4	ND/<3.3	ND/<13
5/2/2016	Walloomsac Road	<b>54.1</b>	4.03	ND/<13
5/3/2016	Walloomsac Road	13.9	ND/<3.3	ND/<13
5/4/2016	Walloomsac Road	ND/<6.7	ND/<3.3	ND/<13
5/10/2016	Walloomsac Road	ND/<6.7	ND/<3.3	ND/<13
5/10/2016	Walloomsac Road	<b>55.1</b>	ND/<3.3	ND/<13
5/10/2016	Walloomsac Road	ND/<6.7	ND/<3.3	ND/<13
5/10/2016	Walloomsac Road	ND/<6.7	ND/<3.3	ND/<13
5/10/2016	Walloomsac Road	ND/<6.7	ND/<3.3	ND/<13
5/11/2016	Walloomsac Road	<b>31.7</b>	ND/<3.3	ND/<13
6/7/2016	Walloomsac Road	ND/<6.7	ND/<3.3	ND/<13
4/19/2016	West Road	ND/<6.7	ND/<3.3	ND/<13
4/19/2016	West Road	ND/<6.7	ND/<3.3	ND/<13
6/8/2016	West Road	ND/<6.7	ND/<3.3	ND/<13
6/8/2016	West Road	ND/<6.7	ND/<3.3	ND/<13
3/9/2016	Westwood Drive	ND/<6.7	ND/<3.3	ND/<13
3/21/2016	Westwood Drive	ND/<6.7	ND/<3.3	ND/<13
3/31/2016	Westwood Drive	ND/<6.7	ND/<3.3	ND/<13
4/12/2016	Whipstock Road	ND/<6.7	ND/<3.3	ND/<13
4/12/2016	Whipstock Road	ND/<6.7	ND/<3.3	ND/<13
5/2/2016	Whipstock Road	ND/<6.7	ND/<3.3	ND/<13
5/11/2016	White Creek road	ND/<6.7	ND/<3.3	ND/<13
4/20/2016	White Oak Drive	ND/<6.7	ND/<3.3	ND/<13
3/1/2016	Wilkie Way	ND/<6.7	ND/<3.3	ND/<13
3/23/2016	Wilkie Way	ND/<6.7	ND/<3.3	ND/<13
4/13/2016	Willow Road	<b>25.1</b>	ND/<3.3	ND/<13
4/13/2016	Willow Road	<b>108</b>	4.96	ND/<13

# North Bennington Private Well Testing Results (PFOA, PFOS, PFHpA)

4/13/2016	Willow Road	28.4	ND/<3.3	ND/<13
4/13/2016	Willow Road	85.9	5.41	ND/<13
4/14/2016	Willow Road	ND/<6.7	ND/<3.3	ND/<13
4/19/2016	Willow Road	77.5	6.73	ND/<13
4/19/2016	Willow Road	31.5	ND/<3.3	ND/<13
4/19/2016	Willow Road	56	ND/<3.3	ND/<13
4/19/2016	Willow Road	ND/<6.7	ND/<3.3	ND/<13
5/3/2016	Willow Road	ND/<6.7	ND/<3.3	ND/<13
5/3/2016	Willow Road	7.01	ND/<3.3	ND/<13
5/3/2016	Willow Road	ND/<6.7	ND/<3.3	ND/<13
5/3/2016	Willow Road	ND/<6.7	ND/<3.3	ND/<13
5/4/2016	Willow Road	89.2	7.8	ND/<13
5/10/2016	Willow Road	75.9	7.78	ND/<13
5/10/2016	Willow Road	76.4	4.64	ND/<13
5/10/2016	Willow Road	ND/<6.7	ND/<3.3	ND/<13
5/11/2016	Willow Road	79.3	5.96	ND/<13
6/1/2016	Willow Road	ND/<6.7	ND/<3.3	ND/<13
	<b>Summary of Sampling Results</b>			
		PFOA	PFHpA	PFOS
	<b>Total Wells with Detections</b>	308	186	2
	<b>Total Wells ND Results</b>	175	297	481
	<b>Total Wells &lt;20ppt</b>	59	163	1
	<b>Total Wells &gt;20ppt</b>	249	23	1
	<b>Total Well Results Received</b>	483	483	483
		Totals do not include multiple samples of the same well or town water supplied samples.* If two different samples fall within two different ranges, the larger concentration is counted.		