








Visit Date	Lake Station	Project ID	Total Nitrogen	Total Phosphorus	Dissolved Oxygen	Temperature	Chla	pH	Cond	
7/2/2018	Bomoseen #1	LaymonQC								
8/27/2021	Bomoseen #1	LaymonQC		